

INSTALLATION INSTRUCTIONS FOR 017086/ 017093

Parts List:



17086 / 017093 Surface Mount Outlet 70077 Surface Mount Outlet Gasket

Installation:

1. Remove plastic cover from gasket to expose the adhesive.




2. Feed the gasket over the cord and apply to back of face of the outlet. Press the gasket down onto the face until adhesive sticks.




INSTALLATION INSTRUCTIONS FOR 017086/ 017093

Installation:

3. Feed cord through the hole in the work surface, and place the power unit into the hole.



4. Once power unit is in hole, slide the bolt brackets outwards so that the bolts clear the housing of the unit.



5. Screw the bolts to the table top until secure.

