assembly instructions

uxl tables (leg installation)

ADDITIONAL TOOLS NEEDED:

POWER DRILL

TOOLS, HARDWARE & COMPONENTS:

- A. uxl work surface
- B. Nyloc bolts (2 per leg)
- c. 5mm allen key extension bit for power drills
- D. uxl leg set



Α.







*legs with casters come with 13mm wrench for securing casters (casters packed with legset).

- $^{\circ}\,$ check that all components are accounted for and undamaged before assembly.
- ° assemble product in a clean, dry area; if cleaning is necessary, use a mild cleaner and damp cloth.
- o for larger units, a second person is recommended for assistance in the assembly process.



- 1. begin by placing your work surface laminate side down on a clean dry area.
- 2. place the threaded holes of the first uxl leg against the frame's leg bracket.
- 3. using supplied 5mm allen key drill bit; attach the bolt and allen key.



hand tighten the nyloc bolt into the hole while holding the leg from behind.



- insert 5mm allen key drill bit into power drill - secure bit in place - and proceed to tighten and secure the nyloc bolts in place.
 - Continue the same assembly process with the remaining uxl legs on your table or desk.
- 5a. for UXL tables / desks with glides flip your table right-side-up (with the help of an assistant) and your table is ready for use.
- 5b. for UXL tables / desks with casters see page 2.

For assistance in assembling product, missing or damaged parts or to place an order, please contact our customer service department @ 1-800-328-1061.

assembly instructions

uxl tables (caster installation)

UXL LEG SETS WITH CASTERS

- A. uxl leg set with casters
- B. uxl caster wrench (13mm)
- c. uxl leg set caster pack



*legs with casters come with 13mm wrench for securing casters (casters packed with legset).

- $^{\circ}\,$ check that all components are accounted for and undamaged before assembly.
- ° assemble product in a clean, dry area; if cleaning is necessary, use a mild cleaner and damp cloth.
- ° for larger units, a second person is recommended for assistance in the assembly process.



 insert caster into threaded hole on bottom of each leg - proceed to hand tighten the nut.



- 2. with the nut hand-tight, use the supplied 13mm wrench to fasten & secure the caster in place.
 - Continue the same assembly process with remaining uxl legs on your table or desk(s).
- 3. flip your table right-side-up (with the help of an assistant) and your table is ready for use.