


Assembly Instructions

Power Units




If you have damaged or missing components,
please contact customer service at 1-800-328-1061

Hardware and Components


POWER UNDER SURFACE MOUNT PACK (PN:12224)

ITEM NO.	PartNo	REV	DESCRIPTION	QTY.
1	12226	B	POWER 2 OUTLETS, 2 USB-C, 1 USB-A, 9.8FT (TR2AUCL)	1
2	12227	B	POWER UNDER SURFACE MOUNT PACK	1



POWER SIDE SURFACE MOUNT PACK (PN:12225)

ITEM NO.	PartNo	REV	DESCRIPTION	QTY.
1	12226	B	POWER 2 OUTLETS, 2 USB-C, 1 USB-A, 9.8FT (TR2AUCL)	1
2	12228	A	POWER SIDE SURFACE MOUNT PACK	1



Assembly Guidelines


Special Notes:

- TOOLS REQUIRED:
 - For Power Under Surface Mount Pack (PN: 12224)
 - Phillips Screwdriver
 - For Power Side Surface Mount Pack (PN: 12225)
 - None
 - **NOTE:** Do **NOT** use impact drills.
- Check that all components are accounted for and undamaged before assembling.
- Please assemble the product in a clean and dry area.
- Clean the product with a mild cleaner and a damp cloth.
- Replacement Hardware Packs:
 - For Power Under Surface Mount Pack (PN: 12224)
 - 12227 Replacement Power Under Surface Mount Pack
 - 69738-R #10X5/8" Wood Screw Pack of 12
 - For Power Side Surface Mount Pack (PN: 12225)
 - 12228 Replacement Power Side Surface Mount Pack


Assembly Instructions

FOR 12224 POWER UNDER SURFACE MOUNT PACK (STEPS 1-4)

1. Unpack and confirm all parts are present. Flip table or desk over on a smooth flat surface for ease of assembly.
2. Place the power unit mount against the top and secure using the four (4) #10 x 5/8" screws with Phillips Bit and Drill. **Do NOT overtighten screws.**



3. We suggest installing the power unit mount flush against the t-mold or edge banding on the edge of the table.
4. If table is equipped with the Power Cord Hook (PN: 60500), wrap the cord around it and clip in the end of the cord into the center clip on the hook as shown. Flip the table back over.




ASSEMBLY COMPLETE


Assembly Instructions

FOR 12225 POWER SIDE SURFACE MOUNT PACK (STEPS 5-8)

5. Unpack and confirm all parts are present.
6. Slide the power unit mount against the top edge as shown.



7. Turn the mounting knob clockwise to tighten the clamp to the table top.
8. If table is equipped with the Power Cord Hook (PN: 60500), wrap the cord around it as previously shown in Step 4.



ASSEMBLY COMPLETE